



ASBESTOS CONSULTING SERVICES

CLIENT: Large national property management company

LOCATION: Multi-story residential building, Boston, MA

Highlights: Facility Inspection, Materials Sampling, Analysis, Management Planning, Project Design, Project Management, Air Sampling

Environmental Services, Inc. (ESI) was requested by its client, a national real estate management company, to provide inspection, sampling, project design, and air monitoring for a property in Boston, MA which required abatement of its hazardous materials. Another local company had failed to provide the services contracted for.

ESI professionals provided an inspection, analysis of suspect materials and a project design expeditiously which enabled the client to begin the critical abatement phase of the project.

During abatement ESI provided

- Project Management
- Performed air monitoring during abatement and clearance samples
- Submitted final documentation to the regulatory agencies for project completion